

NAVIGATION**Buoy Changes in Swallowtail and Whitaker Navigation Channels**

Mariners are hereby notified of the following alteration to navigation marks in the Swallowtail and Whitaker Channels as of 15th June 2021. Please find attached chart [not to be used for navigation].

Swallowtail Channel

- **Swallowtail No 1 LT Buoy** has been moved to a new position of:
51° 41.400N - 001° 07.500E
Colour, top mark and light characteristic Fl. Y. 5s remain unchanged.
- **Swallowtail No 2 LT Buoy** has been permanently withdrawn
from **51°41.184N 001°06.296E**
- **Swallowtail No 3 LT Buoy** in position **51°40.843N 001°04.391E** has been renamed Swallowtail No 2
New light characteristic is Fl. Y. 10s
Colour, shape and top mark remain unchanged.
- **Swallowtail No 4 LT Buoy** in position **51°40.519N 001°03.487E** has been renamed.
Swallowtail No 3
Light characteristic unchanged Fl. (2) Y. 10s
Colour, shape and top mark remain unchanged.

Whitaker Channel

- **Whitaker No 1 LT Buoy** has been moved to a new position of **51°40.530N 001°05.400E**
Shape, colour, top mark and light FL. G. 5. remain unchanged.
- **Whitaker No 2 LT Buoy** has been moved to a new position of **51°40.250N 001°05.400E**
Shape, colour, top mark and light Fl. R. 5s remain unchanged.
- **Whitaker No 3 LT Buoy** has been permanently withdrawn from **51°40.424N 001°04.719E**
- **Whitaker No 4 LT Buoy** has been permanently withdrawn from **51°40.161N 001°04.912E**
- **Whitaker No 5 LT Buoy** in position **51°40.038N 001°03.217E** has been renamed Whitaker No 3 LT Buoy.
New light characteristic is Fl. (2) G. 5s
Shape, colour and top mark remain unchanged.
- **Whitaker No 6 LT Buoy** in position **51°39.757N 001°03.478E** has been renamed Whitaker No 4 LT buoy.
New light characteristic is Fl. (2) R 5s
Shape, colour and top mark remain unchanged.
- **Whitaker No 7 LT Buoy** in position **51°39.540N 001°02.000E** has been renamed Whitaker No 5 LT Buoy.

New light characteristic is Fl. (3) G. 10s
Shape, colour and top mark remain unchanged.

- **Whitaker No 8 LT Buoy** in position **51°39.351N 001°02.000E** has been renamed Whitaker No 6 LT Buoy.

New light characteristic is Fl. (3) R. 10s
Shape, colour and top mark remain unchanged.

Captain Susan Harrison MNM
Harbour Master
16th June 2021